


PREPARED BY  
U.S. SOIL CONSERVATION SERVICE  
THROUGH THE  
WILL-SO. COOK SOIL & WATER CONSER. DIST.

IL-33-07




Section 16  
Joliet Twp.

SLOPE FACTORS

EROSION FACTORS

NO NUMBER = MORE THAN 6" OF TOPSOIL REMAINS  
2 = 3-6" OF TOPSOIL REMAINS  
3 = 0-3" OF TOPSOIL REMAINS  
6 = MULTIPLE EROSION CLASS



EPA Region 5 Records Ctr.



300645

